



Postal Address:
 Suite 2002a, Level 20
 44 Market Street
 Sydney, New South Wales 2000
 Australia

Testing. Advising. Assuring.

| | | |
|---------------------------------------|--|--------------------|
| EWFA CERTIFICATE OF ASSESSMENT | CERTIFICATE No : SFC 41267300.1 | Page 1 of 1 |
|---------------------------------------|--|--------------------|

| Report Sponsor | Certificate Issue Date | Product Name |
|--|------------------------|---|
| Matilda Veneer Pty Ltd 18-22 Activity Cres Molendinar QLD 4214 | 20/07/2016 | Matilda Fireply FR treated plywood wall and ceiling lining |

| Referenced Assessment Report | Referenced Standards | Report Issue Date | Report Validity Date |
|------------------------------|----------------------|-------------------|----------------------|
| EWFA 41267300.1 | AS5637.1-2015 | 20/07/2016 | 30/04/2021 |

Introduction

The element of construction described below was assessed by this laboratory on behalf of the report sponsor in accordance with the stated test standard and achieved the results stated below. Refer to the referenced assessment report(s) or Regulatory Information Report(s) for a complete description of the assessed construction.

Description of Assessed Product and Performance

The scope of the assessment includes the Group Number and Average Specific Extinction Area of Matilda Fireply FR treated plywood wall and ceiling lining between 6mm and 50mm thick when assessed in accordance with AS5637.1: 2015.

Group Number: 1
Average Specific Extinction Area: <250m²/kg

Refer to the referenced assessment report(s) or Regulatory Information Report(s) for a complete description of the assessed construction.

Conditions/Validity

- THIS CERTIFICATE IS PROVIDED FOR GENERAL INFORMATION ONLY AND DOES NOT COMPLY WITH THE REGULATORY REQUIREMENTS FOR EVIDENCE OF COMPLIANCE.
- Reference should be made to the relevant assessment report(s) or Regulatory Information Report to determine the applicability of the test result to a proposed installation. Full details of the constructions and justification for the conclusions given, along with the validity statements, are given in the assessment report(s) or Regulatory Information Report(s).
- The results of these fire tests may be used to assess fire hazard, but it should be recognized that a single test method will not provide a full assessment of fire hazard under all conditions.

| | | |
|--------------------------|---|---------------------------|
| TESTING AUTHORITY | Exova Warringtonfire Aus Pty Ltd | |
| Address | Suite 2002a, Level 20, 44 Market Street, Sydney NSW 2000, Australia | |
| Phone / Fax | +61 (0)2 8270 7600 / +61 (0)2 9299 6076 | |
| ABN | 81 050 241 524 | |
| Email / Home Page | www.exova.com | |
| Authorisation | Prepared By: D. Nicholson | Reviewed By: S. Hu |